RECEIVED

tevised 02/03

CORRES. CONTROL INCOMING LTR NO.

20276 RF03

2003 HAR 24 PSTATE OF

Bill Owens, Covernor Douglas H. Benevento, Executive Director

CORRESPONDENCE

Douglas H. Benevento, Executive Director CONTROL

Dedicated to protecting and improving the health and environment of the people of Colorado

DUE DATE ACTION

4300 Cherry Creek Dr. S. Denver, Colorado 80246-1530 Phone (303) 692-2000 TDD Line (303) 691-7700 Located in Glendale, Colorado

Laboratory and Radiation Services Division 8100 Lowry Blvd. Denver, Colorado 80230-6928 (303) 692-3090

Colorado Department of Public Health and Environment

http://www.cdphe.state.co.us

DIST. BERARDINI. J. H CROCKETT, G. A DECK, C. A. DEGENHART, K DIETER, T. J DIETERLE, S. E FERRERA, D. W FERRI, M. S GERMAIN, A. GIACOMINI.J.J ISOM, J. H INDSAY. LONG, J. W

MARTINEZ, L. A

SHELTON, D. C

TUOR.N. R

WILLIAMS, J.

PARSONS D

FREIBNINC

Benussaed n

NESTA.5

NAGEL, R. E.

NORTH, K. PARKER, A. M March 21, 2003

Mr. Richard DiSalvo Acting Assistant Manager for Environment and Stewardship U.S. Department of Energy, Rocky Flats Field Office 10808 Highway 93, Unit A Golden, CO 80403-8200

RE: Reconnaissance Level Characterization Report (RLCR) for Buildings 549, 554, 556, and 681 -Concurrence

Dear Mr. DiSalvo:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the RLCR for Buildings 549, 554, 556, and 681, Revision 0 dated February 20, 2003, received on March 3, 2003. Based on the information contained in this RLCR (including the additional information and revisions provided on March 10, 2003), we are hereby concurring with the determination that Buildings 549, 554, 556, and 681 are Type 1 Facilities.

Although these facilities may be identified as Type 1 facilities, it must be noted that B554 and B556 are located within the boundary of ER IHSS Group 500-2. The potential contamination associated with Group 500-2 includes organics, metals, and Rads that may have been released into the environment prior to construction of B556 and adjacent to B554. As such, during the demolition of B554 and B556, particularly removal of B556 slab, appropriate precautions need to be included in the scope of this demolition activity. In addition, ER needs to be consulted and appropriately integrated into these removal activities to allow for sampling as necessary and appropriate characterization of the waste generated.

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328.

COR. CONTRO ADMN. RECOR

> Sincerely, Reviewed for Addressee Corres. Control RFP

Steven H. Gunderson RFCA Project Coordinator

cc:

Steve Tower, DOE Tim Rehder, EPA

> Duane Parsons, KH Lane Butler, KH

Administrative Records Building T130G

Cameron Freiboth, KH Dave Shelton, KH Steve Nesta, KH Marla Broussard, KH



ADMIN RECORD IA-A-001323

Ref. Ltr. #

DOE ORDER # 5400-1